



Factsheet

Sales enquiries:
sales@palmermetals.co.uk

Visit our website:
www.palmermetals.co.uk

Magical Crimping Pliers: Crimping Technique

The jaws of the Magical crimping plier are shown here. There are two sizes of plier one for .014/.015" beading wire and the other for .018/.019"



Step 1 of the crimping process is to thread the correct size crimp tube onto your stringing wire. Pass the wire through the clasp, jump ring or whatever you are placing on the end of the wire and then back through the crimp tube to end up looking like the picture on the left. Make sure that the two wires lie next to each other and are not crossing over each other.

Step 2 while holding wire side by side, place crimp tube inside the groove of the Magical Crimping Pliers and squeeze down.

Step 3 crimp tube should now look like this, resembling a square.

Step 4 Turn crimp tube on side, making sure the top of the square is up. Place inside Magical Pliers and squeeze down. Turn and squeeze two times.

Step 5 This what the final crimp should look like. It should have a nice round or oval shape.



PALMER METALS
LTD

Specialists In Precious Metals